



Sustainability

Verification

Operating Manual



Profitability

Material Analysis



TABLE OF CONTENTS

Ran Materials Verification

Profitability

Material Analysis

Sustainability

3

Introduction	3
Warnings & safety	4
Installation	5
Specifications	7
Operation & cleaning temperatures	9
Procedures for cleaning PVC	12
Fault finding & Parts list	13
Wiring Diagrams	15
Exhaust diagrams	16
CE Declaration of Conformity	20



From lab to production, providing a window into the process

INTRODUCTION

Fluidized Temperature Baths have been in use for decades as a temperature source for many heating applications such as thermal cleaning, heat treatment, calibration, thermal analysis, process heating and laboratory reactive heating. It is important that this instruction manual be made available to all operators who may come in contact with the system. All operators should read this manual from beginning to end and observe all safety warnings and symbols. In particular, we would stress the importance of standard, commonsense rules and adherence to normal, safety standards and procedures. Maintenance and/or service should only be performed by a qualified electrician or engineer. If there is any doubt whatsoever relating to the proper use of this equipment, please contact us.

Profitabi

Material Analysis

Sustainability

The Fluidized Temperature Bath consists of a stainless steel tank and top cover that is surrounded by a powder coat painted outer case. This tank either contains or is surrounded by electrical heating elements and is wrapped with an insulation blanket. Temperature and air control systems as well as other electrical components are housed with a forced air cooled control cabinet that is mounted on the side. The temperature of the fluidized temperature bath is set and maintained by temperature controller, which receives an electrical signal from a type "K" thermocouple placed along the fluidized bath container inner wall. Current to the heating elements is switched on and off by means of solid state relay actuated by the temperature controller. The controller has a resolution of 1º and can be switched between °C and °F.

The systems are supplied with independent over-temperature protection via a 2nd thermocouple junction that will disable power to the heaters in the event that one of the following conditions occur; thermocouple failure, loss of power to or controller fault and/or exceeding the factory set high temperature limit of 618°C(1145°F). The internal controller will flash a message when one of these conditions has occurred and/or light up the front panel neon light labeled "Overtemp".

Air enters into a seam welded air chamber in the bottom of the tank that causes the aluminum oxide to Fluidize. The air supply to the Fluidized bath must be clean and dry and adjusted to supply a constant 40 PSI/2.7 bar of pressure at a maximum flow of 3.5 CFM/99LPM. An air filter and pressure regulator can be supplied as optional equipment . Air flow to the Fluidized Bath is controlled automatically by 3 solenoids which are connected to 4 needle valves to set and control air flow at various temperature points. Alarms ALM1, ALM2 and ALM3 are used to control air flow and are not indicative of any fault condition.

WARRANTY

This product is covered by a 1 year factory parts and labor warranty. It must be clear that **Dynisco** and our suppliers are not insuring your products/premises or guaranteeing that there will not be damage to your person or property if you purchase our Products. **Dynisco** or our Suppliers shall not be liable under any circumstances for damage to your person or property or some other person or that person's property by reason of the sale or use of the product we sell, or its failure to operate in the manner in which it is designed. **Dynisco** and our Suppliers liability, if any, shall be limited to the original cost of the Product only. Use of this Product is at your own risk. Buyer assumes full responsibility in determining the suitability of these items for buyers intended use. It must be clear that the Warrantors are not insuring your products/premises or guaranteeing that there will not be damage to your person or property if you



use products purchased from Accurate Thermal Systems. WARRANTORS' OBLIGATION UNDER THIS WARRANTY IS LIMITED TO REPAIR OR REPLACEMENT OF THE PRODUCT ONLY. THIS WARRANTY DOES NOT COVER PAYMENT OR PROVIDE FOR THE REIMBURSEMENT OF PAYMENT FOR INCIDENTAL OR CONSEQUENTIAL DAMAGES.

WARNINGS AND SAFETY

Please read this entire manual before operating the Fluidized Temperature Bath. If used improperly a serious personal injury can occur and/or cause damage to the system. Our products are designed and manufactured to conform to internationally recognized safety standards and requirements. Accurate Thermal Systems, its representatives, vendors and distributors assume no liability for the operation of this product in an unsafe manner. Use common sense and adhere to all warnings and cautions during use

High temperatures can cause serious burns and ignite combustible materials. Please be aware of and conform to the following. The symbols shown may appear in this manual or on the product.





ATTENTION





PROTECTIVE CONDUCTOR TERMINAL

<u>WARNINGS</u>

- WEAR PROTECTIVE GLOVES that are rated for 1000°F/525 °C that cover your hands and arms up to the elbow
- **DO NOT** use the system near flammable liquids or gases
- **Provide at least** 12"/305mm of open space around the system and 4 ft/1200mm above it to prevent surrounding objects from getting hot.
- After removing parts, baskets and any other heated items from the system remember that they may be VERY HOT
- Never add cold aluminum oxide sand to the Fluidized Bath when it is above 400°F/200 °C
- **Eye goggles** that are not vented should be worn when working with the system to protect eyes from heat and aluminum oxide sand

CAUTION

- **DO NOT** use the Fluidized Bath if the control box fan is not running
- **DO NOT** operate the system if it is not Fluidizing/bubbling or is appears that a portion is not Fluidizing as normal
- DO NOT place any fluids or liquids directly into the bath
- DO NOT use the Fluidized bath if the surrounding area or floor becomes wet
- If the "OVERTEMP" light comes on, DO NOT shut off power but instead contact maintenance or a qualified technician immediately.
- In the event of a power loss leave the air supply on and flowing if possible





PACKAGING, HANDLING & TRANSPORTATION

Inspect all shipping containers for signs of damage which may have been caused by rough handling in transit. Immediately take pictures of any damage to the packing. If the packaging is damaged carefully unwrap all items to inspect for damage. Also take pictures of any damaged product and then immediately contact the Freight Company and Accurate Thermal Systems.

erification

Sustainability

Remove the packing list and verify that all ordered items have been received. If there are any questions about the shipment, please call Dynisco at 1-800-

Retain the cartons in which the bath was received until the unit is tested and found to be in good condition.

Fluidized Temperature Bath Systems weigh in excess of 120lbs/55kg and should only be moved by using a hand truck, pallet jack or fork lift. When transporting a system it must be palletized on a suitable skid due to the weight and size.

INSTALLATION

	1.	1. The bath should be placed in a location that is level and dry. Check the system for levelne			
	2.	should be located in an are For thermal cleaning applic proximity to an exhaust ho the diagrams on PAGE 19 fr	a where suitable power and air are ava ations the system installation should b od or exhausting pipework for removin or more details on exhausting	ailable. be in an area within close ng of fumes and smoke. See	
	3.	 Due to the radiated heat from the system install in a location that allows at least 12"/30 clearance on the sides and 4ft/122cm above to prevent surrounding objects from gettin 			
	4.	Connect an air supply set to CFM/99 LPM. The supply set can cause damage to the sy assistance with air filtering should be used to connect the control box.	o deliver a constant 40 PSI/2.7 BAR at a hould be dry and free of particulate. An ystem and/or components that are imp and drying. A 6ft/180cm length of %"/ the air supply to the bath via the quick	maximum flow of 3.5 n air supply that is not dry mersed into it. Contact us for '10mm OD rigid tubing c disconnect fitting on rear of	
	5.	5. Before connecting to your electrical supply verify that it meets the specifications for the ur as shown on the rating plate. The requirements below must be met to maintain safety to equipment, personnel and property. ALL ELECTRICAL CONNECTIONS MUST BE MADE BY A QUALIFIED ELECTRICIAN OR ENGINEER. The system is supplied with a 10ft/305cm length of appropriately rated power cable for each specific model. Below are recommended wire siz for the power feed up to the breaker panel and the recommended breaker ratings.			
-		Model	Supply conductor size to breaker panel – 300 volt rating	Switchable panel breaker rating	
		PC-FB-12L	12 gauge or 3.31mm ²	20 amps/ 250 VAC	
		Fluidized Bath wiring connections			
		Live	Black		
		Neutral	White		





Profitabi

Material Analysis

Sustainability



your operating temperatures are controlled automatically by the PC and software.

lerification

Sustainability

Profitability

Material Analysis

TECHNICAL SPECIFICATIONS Overall external dimensions:	length: 21"/53.3cm width: 24"/61cm height: 27"/68.5cm		
Bath internal dimensions:	10.0"/25.4cm diameter 16.0"/40.6cm deep		
Working volume:	10.0"/25.4cm diameter (8.4"/21.3cm diameter when using parts basket) 12.0"/30.5cm deep		
Temperature range:	50°C to 605°C (122°F to 1121°F)		
Temperature stability: at set point)	±1.0º C (8"/20cm immersion depth, with lid on after 2 hours controlling		
Display accuracy: at set point)	$\pm 5.0^{\circ}$ C (8"/20cm immersion depth, with lid on after 2 hours controlling		
Heat up time*:	Ambient to 900°F, 480°C – 2.0 hrs		
Air supply:	Clean, dry and oil free air, at a constant pressure of 40 psi/2.7 bar, max flow of 3.5 CFM/99 LPM using a ¾"/10mm OD rigid tubing plugged into the quick release fitting on the control box.		
Fluidizing bath media: Aluminum oxide 85lbs/38.6 kg			
Electrical requirements: 240V, 1 phase, 60Hz, 4.5kW, 18.7 amps, fuse rating 20 amps/250V			
Exhaust fan requirements:	250 ft ³ /min. at 1 in W.G.		
Gross weight:	195 lbs/88.6 kg		
Net weight:	FTBLL12 - 110 lbs/50kg		

Operating Ambient: 10 ° C/50 ° F to 40 ° C/104 ° F, 80% RH max.

Alum Oxide

* Indicated heat up time applies for a well fluidized bath with a lid on, extraction fan off and power supply voltage of 220 to 240 VAC under load. Note that a supply voltage below these values can damage the solenoid values and reduce heat up time and bath performance.

- 85 lbs/38.6 kg



OPERATION

The FTBLL Fluidized baths in this manual were designed specifically for "burning off" or thermally removing residue from plastic machinery tools. The FTBLL baths are also a good choice for many heat treatment, reactive chemistry, calibration and exothermic reaction type of applications.

Profitab

Material Analysis

Sustainability

Our systems are effective on all plastics, including polyethylene, polypropylene, PVC, nylon, polyester, polycarbonates, acrylic, Peek, PTFE, polystyrene and acetyl. In addition, they are effective with rubber, EPR, epoxy resins and acrylic paints. They provide a safe, dry and fast means of removing all plastic residues with a minimum amount of effort. The "burning off" operation is controlled at a uniform temperature so that distortion is avoided. Furthermore, the fluidized temperature bath is non-abrasive, so physical damage to parts is minimal which extends tool life.

The cleaning process itself is very simple using the heat transferred from the fluidized bath to the tools to degrade the plastic residue. Parts are placed in a mesh basket for ease of handling, then lowered into the fluidized bath, operating at a temperature between 800°F (425°C) and 1020°F (550°C) depending on the polymer, for approximately 30 to 60 minutes. Actual burn off times and temperatures vary depending upon the weight, material being removed and overall quantity of residue on the part.

BATH TEMPERATURE

The bath should be allowed to stabilize for at least 1 hour after the controller has reached the set point temperature before using the bath. An initial temperature drop or quenching of the bath can occur after inserting objects into the bath. This temperature drop depends on the size of the immersed object, but is generally in the order of 27°F (15°C). Polymer is reduced to ash and carbon dioxide quickly above 752°F (400°C). It may be found desirable to pre-heat the bath to as high as 1020°F (550°C) in order to obtain quick results, but caution should be exercised not to damage tools by overheating or to cause a flame up due to combustion of polymer and fumes.

THE CLEANING PROCESS

The first two thirds of the total time required for tool cleaning, sees the plastic reduced to a tar mix state. In this phase, all the initially combustible products of the plastic leave the bath through an appropriate fume extraction system. In the last third of the immersion time, the tar mix state is reduced to carbon which either burns away or remains loosely bound to the tool. In the latter case, it can be blown off with shop air or lightly brushed off with a wire brush or Scotch Brite pad after the part is removed from the fluidized temperature bath. The clean part can then be set aside to cool or be placed in the optional cooling stand and sieve accessory (PC-FB-CLRACK) before being used or returned to the tool room. In some cases, dies may need to be wiped off or polished gently with a soft cloth.

The aluminum oxide fluidizing medium is not degradable but will need to be replenished due to loss during operation or extracted in the exhaust. In the particular case of PVC, chlorinated hydrocarbons remain in the fluidized bath after burn off which dictates special maintenance procedures. When removing PVC we recommend leaving the system to run at lower temperatures (100°C/200°F) when not in use to minimize moisture ingress into the aluminum oxide which can increase Hydrochloric acid levels in the bath resulting in oxidation and damage to metal components.



TYPICAL CLEANING TEMPERATURES

The following table details recommended operating temperatures for particular Polymers. The temperatures quoted should be used as an initial guide only. The ideal operating temperature will vary depending on the size of the parts and the amount of material being removed. Temperatures below 400°C/750°F should be avoided to eliminate the danger of the polymer melting and sinking to the bottom of the bath where it may block the porous plate. With large objects it is desirable to heat the bath to above the operating temperature so that the polymer rapidly moves through the melting phase to the burning condition. Excessive operating temperatures should be avoided as they increase the fume concentration and may result in a flame up of the parts in the bath.

Use as a guide & starting point only. Always use the lowest temperature that gives satisfactory results <u>Material Burn-off temperature °C/°F</u>

Nylon 450/842 Polyethylene 425-450/797-842 PTFE 500/932 PEEK 500-525/932-977 Ethylene methacytic 450-480/842-896 Rubber debonding 350/662 Crosslink PE 400/750 Paint 475-575/887-1067 Polypropylene 425-500/797-932 PVC 460-540/860-1004 Silicone Rubber 535/995 Polyurethane 440-450/824-842 Polycarbonate 400-425/752-797 Styrene 450/842 Flouropolymers 525/975 High density polythene 450/842 Polyesters 450/842 Polystyrene 450/842 Organic matter oil/grease 300-500/572-932

Material Analysis

Sustainability

Profitab

PID TEMPERATURE CONTROLLER

The control parameters in the PID temperature controller have been optimized by the factory to give the best results for most applications.

- 1) To change the set point use the up/down buttons to set a value. The \square key can be used to switch between display digits for fast set point changes. Press \square to accept any changes.
- 2) The controller has been locked out to prevent accidental parameter changes. This is confirmed by the key symbol $\frac{1}{2}$ in the display.
- 3) To unlock the controller press the raise key and the down arrow at the same time. The display will show **KEYP**. Use the up arrow to select all zeros 0000 and then press raise.
- 4) Press the Rev to access the PVOF parameter which is used to set a calibration offset. This can be used to correct any errors between an independent thermometer and the controller display.
- 5) To lock out the controller, press the C key until LoC is displayed. Use the up arrow to select LoC2 and then press C.

PC SOFTWARE FOR WINDOWS

A PC software package for Windows is available for free download from our website. This software allows you to remotely control the bath temperature, display a temperature graph and put the bath on a weekly operation schedule whereby it will follow the program you create and cool down to a set temperature after hours and then heat up and be ready for operation in the morning.



FUME REMOVAL

See the diagrams on page 19 for examples on designing a fume exhaust system. When the Fluidized Temperature Bath is installed with a fan and exhaust ducting system, fumes will be removed from the top of the fluidized bath or through the extraction collar depending on the exhausting layout used.

Profitab

Material Analysis

Sustainability

The Cyclone is used to capture any sand and heavier particulate from the exhaust stream before being vented away from the system. We have three different potential system layouts for venting and exhausting fumes and smoke from the work area.

PC-FB-CYCLONE -

An efficient in-line unit for removing aluminum oxide media and heavy particulate from the exhaust fumes.

PC-FB-HEPA-FLTR-V - DCS2500 Vertical Air Filtration System.

PC-FB-HEPA-FLTR-H - DCS2500 Horizontal Air Filtration System.

OPERATOR BASIC MAINTENANCE

The control box cooling fan should be cleaned out with shop air periodically to keep it free from dust and particulate.

The aluminum oxide, not being degradable, will only require replacement when losses occur due to attrition, spillage or when becomes contaminated with carbon and ash. Note that the aluminum oxide pulled out of the bath through the exhaust duct can be captured for reuse with the "cyclone" option (PC-FB-CYCLONE).

On at least daily intervals, the bed should be cleaned of floating residues by means of a wire mesh hand sieve or conventional kitchen hand strainer. This procedure removes carbon char clumps which impairs fluidization and acts as an absorbent. More importantly, it can also remove uncharred plastic and so reduce the quantity of fumes produced and the time of processing. If you find clumps in your bath in daily use in should be emptied monthly to check for buildup of clumps and heavy deposits in the bottom of the tank.

The optional air-line filter/regulator into the bed is self-draining. However, it should be kept in good condition by inspection at two week intervals and by cleaning the bowl and washing or replacing the filter element as necessary. With exceptionally dirty or wet air supplies this frequency may have to be increased. Water or water vapor in the air supply is a notorious source for the production of hydrochloric acid in the bed when PVC is burned off. In addition, oil vapors in the air supply which reach the fluidizing plate are carbonized within the pores of the plate, quickly causing blockage and consequent poor fluidization. Corrosion of processed parts could be seriously increased if they are left immersed overnight. Furthermore, residual plastic, instead of being burned off in a fluidized state, could percolate down through a static bed and settle on the porous plate causing blockage and poor fluidization.

All ventilation ductwork and components should be visually inspected every 3 months for signs of



buildup and possible blockage. A buildup of oil and grease from pyrolyzing plastic in the ductwork can be a fire hazard and should be cleaned or the ductwork replaced.

If the bath is left unused for long periods of time, empty the aluminum oxide and store it in a separate container. Keep the inside of the bath clean and dry.



SPECIAL OPERATOR MAINTENANCE PROCEDURE WHEN BURNING OFF PVC OR OTHER HALOGENATED POLYMERS

Burning off PVC (polyvinyl chloride) and Fluoropolymers in a Fluidized Temperature bath offers one of the most severe conditions of operation. Hydrogen chloride (HCl) liberated on the breakdown of PVC is absorbed by the bed medium creating an acidic environment within the bed. This happens especially when the bed also absorbs water from the atmosphere or when the fluidizing air is cold. HCl is extremely corrosive, especially when it is aerated and wet. In addition, in water it produces chloride ions which, even in neutral or alkaline solutions, promote corrosion and rusting in steel. A common example would be the corrosive nature of sea water and calcium chloride road deicer.

Profitab

Material Analysis

Sustainability

Consequently, fluidizing baths used for burning off PVC require maintenance to minimize corrosion of the bath and of parts cleaned in it, especially if they are not stainless steel. The purpose of most of the recommended maintenance procedures is aimed at keeping the bed medium clean, free-flowing, free of gums, acid, partly decomposed plastic, char and larger particles. These cleaning processes have the additional benefit of ensuring good fluidization and thus good heat transfer throughout the bed and into immersed parts. This, in turn, reduces burn-off time, uneven heating of parts and thus distortion, increases heater life by eliminating localized hotspots and makes cleaning easier on a regular basis.

The following procedures are essential when PVC is burned off on a regular basis, but they can also be followed by users of other plastics.

The bed should be completely emptied at monthly intervals and visually inspected for signs of corrosion. Examination should include the walls of the inner cylinder, the porous fluidizing plate, the thermocouple sheath and the loading baskets with particular emphasis on exposed weld lines. Serious corrosion should be dealt with immediately by improving maintenance procedures or by replacing the inner container before holes appear and cause failure of the heating element and corrosion in more inaccessible parts.

The aluminum oxide should be sieved with a 50 mesh screen on at least monthly intervals to remove any gummy material, clumps of carbon and ash and then periodically it should be completely changed out with new media.

During shutdown overnight or over the weekend, the temperature should be reduced to 100°C/200°F to ensure that the moisture from the atmosphere is not condensed into the bed to create hydrochloric acid. Fluidizing air should always be kept on. For extended shutdowns exceeding two days, the medium should be removed and the inside of the bath wiped out with a wetted 5% washing soda solution (sodium carbonate) to help neutralize any acid.



FAULT FINDING & MAINTENANCE

Fault finding, electrical troubleshooting and maintenance should only be performed by qualified electrician or service engineer. Always make sure the power supply is disconnected with a lockout notice in place before replacing parts. Refer to the spares list on the next page for any parts that are required.

Verification

Rear Mat

Profitability

Material Analysis

Sustainability

	1. 2.	Poor or no Fluidization – remove aluminum oxide from bath leaving approximately 2 inches in the bottom. If an area ¼ or more is not bubbling then most likely the porous plate is blocked and should be replaced. Check that the porous plate is not blocked with plastic residue or other material. Verify air supply is set to 40 PSI. If OK, see step 11. Slow heat up – Check current draw of the heaters. FTBLL12 at 240volt should be around 18 amps. The FTBLL26 should be 25 amps. Also check that air is flowing at the rates indicated on page 8. Note the flows that should be observed at each temperature range.
	3.	<u>Thermocouple fault</u> – if a open sensor alarm is shown on the controller then check with an instrument that can measure and simulate thermocouple signals to verify its operation. If open then replace the thermocouple
•	4.	"OVERTEMP" light is on - indicates that an over temperature condition has occurred or the limit thermocouple has failed. First verify that air is flowing into the bath and that it is well fluidized with flow rates shown in the table below. Next check to see that the thermocouple connected to the open PCB limit controller on pins 3 & 4 has not failed. Finally make sure that the solid state relay passes current only when a DC signal is output by the controller. The fault condition can be cleared by shorting terminals 1 and 2 on the limit control PCB.
4	5.	No heat – verify heater current. The FTBLL12 should measure 18 amps and the FTBLL26 close to 25 amps. If no current check heater resistance, FTBLL12 = 13 ohms, FTBLL26 = 9 ohms. If OK go to step 6.
	6.	<u>No heat</u> – the controller will output a DC signal to the SSR when heat is called for. If the solid state relay is receiving a DC control signal but not passing power to the heaters then it should be replaced. If OK, go to step 7
	7.	No heat – verify that the contactor coil has voltage across it and that the contacts are closing
	8.	Bath temperature is not accurate, parts not being cleaned – if you suspect that the bath temperature is off it can be checked with a handheld thermocouple meter. Do not use an IR thermometer to measure the sand temperature. If inaccuracy is verified refer to step 1 and 2. If OK the control thermocouple should be checked and replaced is necessary.
	9.	Combustion occurs and parts flame up – reduce operating temperature by 20°C/40°F
	10	Increments until it doesn't happen again.
	10.	Flow rates not meeting table below – verify that the 3 solenoid values are receiving
		power from the controller and replace as necessary.



FLUIDIZING AIR ADJUSTMENT

The system automatically controls the Fluidizing Air to the bath at all times. It is a very reliable and flexible setup however the user can make adjustments to optimize the Fluidization as needed.

The controller is set up with factory defaults to give satisfactory results based on the temperatures and flow switch points shown below. In general it is always preferable to be over-Fluidized than under.

Indicated bath	Alarm LED	Needle Valve	Flow rate – CFM	Flow rate – CFM
temperature			FTBLL12	FTBLL26
up to 174°C (345°F)	ALM1, ALM2, ALM3	1, 2, 3, 4	3.5	3.6
175°C (347°F) to 324°C (616°F)	ALM2, ALM3	1, 2, 3	3.0	3.2
325°C (617°F) to 434°C (813°F)	ALM3	1, 2	2.4	2.6
435°C (815°F) to 605°C (1121°F)	None	1	1.8	2.0



Wiring Diagrams



Profitability

Material Analysis

Sustainability

Verification

(MFR)

西西

Ran Materials



Fume Exhaust Diagram #1





Fume Exhaust Diagram #2





Fume Exhaust Diagram #3





EC Declaration of Conformity

In accordance with EN ISO 17050-1:2004

WeDyniscoof38 Forge Parkway Franklin, MA 02038in accordance with the following Directives:

2006/95/ECThe Low Voltage Directive2004/108/EECThe Electromagnetic Compatibility Directive2011/65/EUThe Restriction of Hazardous Substances Directive

hereby declare under our sole responsibility that:

Equipment	Fluidized Temperature Bath
Model numbers	PC-FB-12L-EU

is in conformity with the applicable requirements of the following documents:

Ref. No.	Title	Edition/dat
		е
BS EN 60519-1	Safety in electroheating installations. General requirements	2011
BS EN 61000-6-	Electromagnetic compatibility (EMC). Generic standards. Immunity for	2005
2	industrial environments	
BS EN 61000-6-	Electromagnetic compatibility (EMC). Generic standards. Emission	2007 +
4	standard for industrial environments	A1:2011

I hereby declare that the equipment named above has been designed to comply with the relevant sections of the above referenced specifications. The unit complies with all applicable Essential Requirements of the Directives.

Signed by: John Czazasty

Name:

Position: Director, Engineering

John Czazasty

Done at Dynisco

On February 17, 2015



Profitabili

Material Analysis

Sustainability

Document number. DC15-FTBLL12